

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Assistant Engineer)

(Re: G.O.Ms. 20/70/PWD Dt. 23-01-1970)

Name of the school	:	SEED GLOBAL SCHOOL, MARANCHERY
1. Name of the officer	:	JAYADEVAN P.N
2. Location	:	Tirur Education District/ Ponnani sub-District Malappuram District
3. Period for which the certificate is issued	:	2025-2026
4. Types of Building	:	Number of Block -1 Number of Floors - 3 <u>Ground Floor:-</u> Classroom: 12 W: 8x6x3.88m Staff room: 4.74x6x3.88m Stair room: 6.23x4.3x3.88m Stair room: 2x6.23x3.6x3.88m Stair room: 3x6.23x3.6x3.88m <u>First Floor:-</u> Classroom: 12x8x6x3.88m Staff room: 4.74x6x3.88m Stair room: 6.23x4.3x3.88m Stair room: 2x6.23x3.6x3.88m Stair room: 3x6.23x3x3.88m <u>Second Floor:-</u> Classroom: 3x6x8x3.88m Lab: 9.08x8x3.88m Lab: 9.07x8x3.88m Lab: 13.73x8x3.88m Lab: 16.23x6x3.88m Staff room: 4.74x6x3.88m
5. Nature of Defect if any	:	
a) Foundation and Basement	:	Nil
b) Super structure	:	Nil
c) Doors and Windows	:	Nil
d) Roof	:	Nil
e) Flooring	:	Nil
f) Miscellaneous (Cracks if any)	:	Nil
6. Any major defects notices which will render the building unsafe in any manner	:	Nil
7. Whether maintenance works have been done Properly	:	Yes
8. Whether the structure is sound or not for Conducting classes	:	Sound

Note:-

- 1- The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
- 2- Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

## CERTIFICATE

Certified that the school was inspected by me on 26-May-2025 and found to be fit / unfit to conduct classes for the period **2025-2026** for the reason stated above.

Place: Maranchery

Date: 26/5/2025



  
ASSISTANT ENGINEER  
LID&EW MARANCHERY  
MARANCHERY GP