

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Aast.engineer)
(Reg:G.O.Ms.20/70/PWD dt.23.01.1970)

1. Name of the Officer	JAYADEVAN.PN
2. Name of the School	SEED GLOBAL SCHOOL
3. Location with name of Education District/Sub.District	Ponnani,Tirur
4. Classification of Building as specified in column 4 of the Application for fitness certificate and size..	1 12 W:8x6x3.88 M G.F,4.74x6x3.88 M, Staff room 2.6.23x4.3x3.88M, 2x6.23x3x3.88M , Stair rooms 3.3x6.23x3.6x3.88 M stair room G.F 4.12x8x6x3.88 m class rooms F.F 5.4.74x6x3.88 M Staff room. F.F 6.6.23x4.3x3.88 M,2x6.23x3.6x3.88 M stair room .F 7.3x6.23x3x3.88 M stair room. F.F 8.3X6X8X3.88 M class rooms 9.9.08x8x3.88M,9.07x8x3.88M Lab Second Floor 10.13.73x8x3.88M,16.23x6x3.88 M Lab second flo 11.4.74x6x3.88 M Staff room second floor

Period for which the certificate is issued 2026-2027

5. Nature of defects, if any a)Foundation and basement b)Superstructure c)Doors and Windows d)Wood work wrought and put-up e)Roof f)Flooring g)Miscellaneous (Cracks.etc)	NIL
--	-----

7. Any major defects noticed which will render the building. : NO
 Unsafe in any manner.

8. Whether Maintenance Works have been done properly : YES


9. Whether the structure is sound or not for conducting classes : Yes the school is Sound under Normal weather Conditions.


Note:1. The stability of the structure should be examined also with reference to location, attitude ,intensity of wind exposure of flood etc.2.Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 19/05/2026.. and found to be fit/unfit to conduct classes, for the period **2026-27** . for the reasons stated above

Place . Maranchery
Date 29/05/2026




അസിസ്റ്റന്റ് എൻജിനീയർ
എസ്. എസ്. ജി. ഡി. സെക്ഷൻ
 (Seal) മാറഞ്ചേരി ഗ്രാമപഞ്ചായത്ത്
Assistant Engineer
 പിൻ : 679581